

Ohio Department of Transportation

Prebid Questions

Project No. 105002

Sale Date - 4/1/2010

Question Submitted: 3/23/2010

Question Number: 1

For bidding documents: if I click on proposal, it says no documents found. Why?

Question Submitted: 3/29/2010

Question Number: 2

Could the existing plans be made available online?

<ftp://ftp.dot.state.oh.us/pub/Contracts/Attach/CLA-84967/>

Question Submitted: 3/30/2010

Question Number: 3

The detail for Anchor Bolt Repair as shown on plan sheet 49B is not part of the work required for this project unless damaged is caused to the existing concrete foundations during removal/reinstallation of Overhead Sign Structure, is this correct?

The intent of the detail is to provide an acceptable method of repair should the anchor bolt be damaged for any reason.

Question Submitted: 3/30/2010

Question Number: 4

Plan Sheet 60 of 67 appears to show patching of the beam seats under 4 1/2 beams. There is no Jacking and Temporary support item, for the beams to be raised in order to perform this patching. What is the intent?

The only patching that is to be done is those areas that can be accessed without jacking.

All prospective bidders, subcontractors, suppliers, materialmen and all others who have an interest in these prebid questions and answers are advised that these items are being provided for informational purposes only and are not part of the bidding documents. If a question warrants a clarification, the Department will issue an addenda addressing the request for clarification to all plan holders. If the Department believes that the bidding documents adequately address the request, the contractor will be advised accordingly.