

Ohio Department of Transportation

Prebid Questions

Project No. 040523

Sale Date - 10/20/2004

Question Submitted: 10/1/2004

Question Number: 1

In regards to Reference No. 018(Light Pole Remove), 020 (Power Service Removed), 021 (Commercial Sign Removal), and 023 (Flag Pole Removed); Are these items to be removed and disposed of, stored, or re-erected in the future?

As per section 202.01, "all 202 items shall be removed and disposed of" unless otherwise specified in the plans.

Question Submitted: 10/15/2004

Question Number: 2

RE: Trench Repair for storm lateral crossings.

1. Where are the pavement repairs paid for?
2. If they are inclusive what thickness of pavement should be placed in the repairs?

Thank You

Please see the Pavement Restoration For Pipe Installation in the General Notes on Sheet No. 11.

Question Submitted: 9/29/2004

Question Number: 3

The Typical Sections (Plan Page 5 & 6)

Shows : 1 3/4" + 1 1/4" of 448 asphalt course and 9" of 302 asphalt base. The thickness of the gutter plate is not given.

Do we increase the thicknes of the 304 aggregate base under the gutter or do we increase the concrete gutter thickness to 12"

Thank You

All prospective bidders, subcontractors, suppliers, materialmen and all others who have an interest in these prebid questions and answers are advised that these items are being provided for informational purposes only and are not part of the bidding documents. If a question warrants a clarification, the Department will issue an addenda addressing the request for clarification to all plan holders. If the Department believes that the bidding documents adequately address the request, the contractor will be advised accordingly.