

# Ohio Department of Transportation - Prebid Questions

Project No. 120057

Sale Date - 2/9/2012

ATH-82817 - SR-550-14.63

*Question Submitted:* 2/7/2012 10:28:00 AM

Line #7 Pavement Repair. What portion of the existing pavement gets repaired ?

**As shown on sheet 2, the repairs are limited to Was-550: 0.88-1.28. The locations are to be determined by the engineer, as per the Item 253 Pavement Repair Note on sheet 6. The intent of the designer is to repair the reflective cracking of the transverse joints and the shoulder failure in the interior of the curve within the given limits.**