

## Ohio Department of Transportation - Prebid Questions

Project No. 130192

Sale Date - 3/28/2013

COS-19794 - VA-BP-FY2013

Question Submitted: 3/22/2013 9:26:34 AM

The 1/2\*3.5 bar depicted on sheet 14/25 should not be metallized since it is being welded to black steel. The EXJ-4-87 spec is incorrect for this application. Nonew extrusion channel or angle are being used. Please confirm.

**The 1/2" x 3½" plate shall be black steel for this application.**