

# Ohio Department of Transportation

## Prebid Questions

Project No. 045021

Sale Date - 6/2/2004

Question Submitted: 5/15/2004

Question Number: 1

- 1.) Plan page 2 Column 1 - Paragraph 6  
Scope of Work - Refers to 881 Microsurfacing with warranty - No other reference to this anywhere.
- 2.) Plan page 2 Column 2 - Paragraph 3  
Crack Sealer, Type 2 or 3  
1,045,999 SY - Specification reads to seal all visible cracks, visual interpretation of this item could lead to a multi-million dollar item. Visual inspection shows the rumac surface on I-271x shows extensive reflective cracking. It is nearly impossible to estimate this item.
- 3.) Plan Page 2 Column 3 - Paragraph 2  
Item 253 Pavement repair as per plan  
a contingency quantity of 600 sy to be used as directed by engineer. 46% of the bid quantity without any idea of size, location, depth etc.
- 4.) Will alternate methods of traffic control be considered?
- 5.) Calculations for partial depth repairs on Page 29 of plans for the following locations seem to be in error.  
IR-480 WB  
Station 1203+00 to 1206+97.21 (397 LF) x (3 LF) should be 132 SY not 206 SY  
Station 1209+12.21 to 1239+00 (2988 LF) x (3 LF) should be 996 SY not 1,549 SY

**Please bid these As Per Plan items as they are described in the bidding documents. Further clarification will be given after the award of the project.**

All prospective bidders, subcontractors, suppliers, materialmen and all others who have an interest in these prebid questions and answers are advised that these items are being provided for informational purposes only and are not part of the bidding documents. If a question warrants a clarification, the Department will issue an addenda addressing the request for clarification to all plan holders. If the Department believes that the bidding documents adequately address the request, the contractor will be advised accordingly.