

Ohio Department of Transportation

Prebid Questions

Project No. 040520

Sale Date - 10/6/2004

Question Submitted: 10/4/2004

Question Number: 1

Item 617, Shoulder Reconditioning, Misc: - Compacted Aggregate, as per plan

Quantity of 569 S.Y. in bid file and on general summary sheets (9/20).

Quantity of 569 C.Y. on Guardrail Sub-Summary sheet (14/20).

569 s.y. is not enough quantity to cover area as referenced in the General Notes.

Is 569 C.Y. the correct quantity?

The estimated quantity in the plan and proposal are correct. This material is required only at the guardrail runs and at spot locations where the existing shoulder is low and not for the length of the work. Payment will be for actual quantity used and revised quantity will be incorporated into the final change order governing completion of the Project.

All prospective bidders, subcontractors, suppliers, materialmen and all others who have an interest in these prebid questions and answers are advised that these items are being provided for informational purposes only and are not part of the bidding documents. If a question warrants a clarification, the Department will issue an addenda addressing the request for clarification to all plan holders. If the Department believes that the bidding documents adequately address the request, the contractor will be advised accordingly.