

Ohio Department of Transportation

Prebid Questions

Project No. 090504

Sale Date - 11/18/2009

Question Submitted: 11/12/2009

Question Number: 1

On page 19/29 of the plans there is a discrepancy with the depth of cover over the box culvert. In the estimated quantities it says 2'-1" min and 3'-4 1/2" max. Below that in the steel area description it says 1.5' to 4'. If it is below 2' distribution steel will be required that isn't in the plans. Which depth of cover is correct?

No distribution reinforcing is required.

All prospective bidders, subcontractors, suppliers, materialmen and all others who have an interest in these prebid questions and answers are advised that these items are being provided for informational purposes only and are not part of the bidding documents. If a question warrants a clarification, the Department will issue an addenda addressing the request for clarification to all plan holders. If the Department believes that the bidding documents adequately address the request, the contractor will be advised accordingly.