

Ohio Department of Transportation

Prebid Questions

Project No. 090448

Sale Date - 9/16/2009

Question Submitted: 7/29/2009

Question Number: 1

There is a conflict between the box culvert loading shown in the plans and the CMS. The 2008 CMS 706.05 calls for a box culvert per ASTM C1577 which is a HL-93 live loading and the plans page 11/25 call for a HS25 live load. It will become a problem when the precast producer attempts to build the box culvert. The precaster will be confused, and probably not build the culvert to the correct loading. My suggestion would be to change the loading on page 11/25 to HL-93.

Question Submitted: 7/29/2009

Question Number: 2

There is a conflict between the box culvert loading shown in the plans and the CMS. The 2008 CMS 706.05 calls for a box culvert per ASTM C1577 which is a HL-93 live loading and the plans page 11/25 call for a HS25 live load. It will become a problem when the precast producer attempts to build the box culvert. The precaster will be confused, and probably not build the culvert to the correct loading. My suggestion would be to change the loading on page 11/25 to HL-93.

All prospective bidders, subcontractors, suppliers, materialmen and all others who have an interest in these prebid questions and answers are advised that these items are being provided for informational purposes only and are not part of the bidding documents. If a question warrants a clarification, the Department will issue an addenda addressing the request for clarification to all plan holders. If the Department believes that the bidding documents adequately address the request, the contractor will be advised accordingly.