

Ohio Department of Transportation

Prebid Questions

Project No. 100166

Sale Date - 3/25/2010

Question Submitted: 3/19/2010

Question Number: 1

Page 4 shows a full depth pavement repair detail for Young Rd boat ramp parking lot. Page 5 talks about surface preparation in the parking lot and gives a repair area of 1500 sy. Page 6 gives a surface preparation area of 1934 sy. There is no bid quantities for pavement repair. Could you please clarify .

The pavement repair is included in the Double Chip Seal, As per plan note on page 5 as part of the surface preparation. That includes the repair for the parking lot and Young Road. The repair for Young Road will be deeper as shown on sheet 4. The total quantity is 1934 syds. for all the repair.

All prospective bidders, subcontractors, suppliers, materialmen and all others who have an interest in these prebid questions and answers are advised that these items are being provided for informational purposes only and are not part of the bidding documents. If a question warrants a clarification, the Department will issue an addenda addressing the request for clarification to all plan holders. If the Department believes that the bidding documents adequately address the request, the contractor will be advised accordingly.