

# Ohio Department of Transportation

## Prebid Questions

Project No. 050563

Sale Date - 11/16/2005

---

Question Submitted:

Question Number: 1

On plan Sheets 88, 89 and 90 you indicate the quantities for the center line and channelizing lines in some locations have 2 lines or sets of lines. When you total the columns you do not double those individual segments. Should these items be APP or do you need to adjust these quantities?

**Answer: The asterisk indicates that the quantity includes two separate lines. Example, Station 655+51 to 657+66 = 215'. This quantity has been doubled for the two lines as noted by the asterisk = 430'.**

Question Submitted: 11/8/2005

Question Number: 2

There needs to be a bid item for Concrete Barrier End Sections, 3 each.

Also, the Concrete Barrier Single Slope Type D, APP Bid item 23.

The As Per Plan note calls for reinforcing as per RM 4.5, does this mean reinforcing only at the end anchors or reinforcing for the entire length of the barrier?

---

All prospective bidders, subcontractors, suppliers, materialmen and all others who have an interest in these prebid questions and answers are advised that these items are being provided for informational purposes only and are not part of the bidding documents. If a question warrants a clarification, the Department will issue an addenda addressing the request for clarification to all plan holders. If the Department believes that the bidding documents adequately address the request, the contractor will be advised accordingly.