

Ohio Department of Transportation

Prebid Questions

Project No. 060478

Sale Date - 11/1/2006

Question Submitted: 10/30/2006

Question Number: 1

In the plan of the temporary support presented, there is no room to do the chipping behind the horizontal w18x86. It would seem that this would require staging the patching. It would seem that a second step will be required to allow all of the required removals - would this be paid for as extra work?

An additional pay item will not be added. All of the work is to be included in Item 519, Patching Concrete Structure, APP.

All prospective bidders, subcontractors, suppliers, materialmen and all others who have an interest in these prebid questions and answers are advised that these items are being provided for informational purposes only and are not part of the bidding documents. If a question warrants a clarification, the Department will issue an addenda addressing the request for clarification to all plan holders. If the Department believes that the bidding documents adequately address the request, the contractor will be advised accordingly.