

### **July 2017 – HY SCDs Updates**

- DM-1.1: Updated Riprap Cutoff Wall notes to reflect changes in C&MS 601.04. (KB)
- HW-2.1: Updated precast notes to reflect changes in C&MS 602.03. (TB)
- HW-2.2: Updated precast notes to reflect changes in C&MS 602.03. (TB)
- HW-1.1, 2.1, & 2.2 moved under the Office of Structural Engineering.