

ODOT District 9 FY20-23 Capital Programs Work Plan

| PID | Project Name | Work Type | Award FY |
|--------|----------------------------------|---|----------|
| 10374 | LAW SR 93 21.32 | Bridge Replacement | 2020 |
| 20617 | LAW-243-9.45 | Bridge Replacement | 2020 |
| 76461 | SCI-US 23-11.48 | Minor Rehabilitation - Pavement Prmy Sy | 2020 |
| 78609 | BRO CR 42A 0.28 | Bridge Replacement | 2020 |
| 91995 | HIG US 62 17.32 | Preventive Maintenance | 2020 |
| 92014 | BRO-SR 353-0.00 | Resurfacing, Undivided System | 2020 |
| 93744 | ROS SR 207 0.00 | New Construction | 2020 |
| 93829 | PIK-124-9.46 | Bridge Replacement | 2020 |
| 96285 | LAW-141-12.98 | Bridge Replacement | 2020 |
| 96292 | JAC-139-12.45 | Bridge Replacement | 2020 |
| 96959 | SCI-73-(11.81)(12.05) | Bridge Replacement | 2020 |
| 97347 | JAC TR 221 2.33 Brdg Replace | Bridge Replacement | 2020 |
| 97977 | D09 Guardrail Project 2020 | Guardrail upgrade/replace | 2020 |
| 97978 | D09 PM FY2020 (A) | Pavement Marking | 2020 |
| 97979 | D09 RPM FY2020 | Raised Pavement Markers | 2020 |
| 97980 | D09 PM FY2020 (B) | Pavement Marking | 2020 |
| 98319 | JAC SR 32 17.58 | Preventive Maintenance | 2020 |
| 98668 | JAC CR 29 8.73 | Bridge Replacement | 2020 |
| 99192 | HIG CR4/VAR Guardrail FY20 | Guardrail Maintenance/Repair (NEW) | 2020 |
| 99193 | HIG CR3 Various PM FY 2020 | Pavement Marking | 2020 |
| 99194 | PIK CR 5/VAR Guardrail FY 2020 | Guardrail Maintenance/Repair (NEW) | 2020 |
| 99195 | ROS CR VAR Guardrail FY 2020 | Guardrail Maintenance/Repair (NEW) | 2020 |
| 99196 | SCI CR VAR Guardrail FY 2020 | Guardrail Maintenance/Repair (NEW) | 2020 |
| 99198 | JAC CR 76 0.00 | Resurfacing, Undivided System | 2020 |
| 99201 | LAW CR 15 0.00 & CR 18 0.00 | Resurfacing, Undivided System | 2020 |
| 100426 | HIG 321 0.00 | Preventive Maintenance | 2020 |
| 100443 | JAC-32-VAR | Bridge Maintenance | 2020 |
| 100477 | ROS SR 104 8.66 | Resurfacing, Undivided System | 2020 |
| 100496 | SCI-US 52-31.24 | Preventive Maintenance | 2020 |
| 100575 | ROS SR 41 3.69 | Resurfacing, Undivided System | 2020 |
| 100587 | LAW SR 522 0.00 | Preventive Maintenance | 2020 |
| 100843 | D09 Microsurfacing FY20 | Preventive Maintenance | 2020 |
| 100846 | ROS-138/207-0.27/3.08 | Preventive Maintenance | 2020 |
| 100849 | LAW-217-13.56 | Resurfacing, Divided System | 2020 |
| 100863 | ROS US 35 25.02 / JAC US 35 1.79 | Preventive Maintenance | 2020 |
| 100887 | JAC-279-10.13 | Bridge Replacement | 2020 |
| 100888 | LAW-775-14.36 | Bridge Replacement | 2020 |
| 100892 | SCI-139-15.00 | Bridge Replacement | 2020 |
| 101388 | HIG CR 10 1.62 Brdg Replace | Bridge Replacement | 2020 |
| 102043 | LAW SR 7 0.66 Rockfall | Rock Slope Maintenance (NEW) | 2020 |
| 102448 | JAC-35-26.10 | Bridge Maintenance/Repair (NEW) | 2020 |
| 102522 | D09-CR-FY2020 | Culvert Construction/Reconstr/Repair | 2020 |
| 102849 | BRO-221-3.91 & VAR | Bridge Maintenance | 2020 |
| 102851 | ROS-35/104-(13.40)(18.12)/25.45 | Bridge Maintenance | 2020 |
| 102888 | BRO SR 763 0.62 Culvert | Culvert Construction/Reconstr/Repair | 2020 |

| | | | |
|--------|----------------------------------|--|------|
| 102889 | LAW-378-2.21 | Culvert Construction/Reconstr/Repair | 2020 |
| 103708 | SCI SR 140 2.05 Safety | Section Improvement | 2020 |
| 103779 | ADA-CR 6B/9B-15.72/30.40 | Bridge Replacement | 2020 |
| 103852 | PIK CR 50 1.95 OH16-01 | Slide Repair | 2020 |
| 105095 | HIG-41-2.02 | Culvert Construction/Reconstr/Repair | 2020 |
| 105099 | BRO-505-5.50 | Culvert Construction/Reconstr/Repair | 2020 |
| 105666 | PIK-104-3.16 | Culvert Construction/Reconstr/Repair | 2020 |
| 105667 | BRO/ROS-32/35-7.43/9.28 | Culvert Construction/Reconstr/Repair | 2020 |
| 106088 | PIK SR 220 12.34 OH17-01 | Slide Repair | 2020 |
| 106089 | ROS US 23 2.49 OH17-01 | Flood Damage | 2020 |
| 106651 | SCI-73-23.01 | Culvert Construction/Reconstr/Repair | 2020 |
| 107076 | PIK CR6/VAR PM FY20 | Pavement Marking | 2020 |
| 107179 | ROS-207-13.55 | Culvert Construction/Reconstr/Repair | 2020 |
| 107284 | SCI Shawnee State Forest Bridge | Bridge Repair | 2020 |
| 107587 | JAC-124-17.55 | Resurfacing, Undivided System | 2020 |
| 108262 | PIK CR 66 2.12 OH18-01 | Slide Repair | 2020 |
| 108287 | JAC SR 32 17.16 OH18-01 | Slide Repair | 2020 |
| 108734 | PIK SR 32 16.08 Safety | Intersection Improvement | 2020 |
| 109297 | D09 HS FY2020 | Herbicidal Spraying | 2020 |
| 109323 | LAW CR 2 3.53 OH18-01 | Slide Repair | 2020 |
| 109348 | ROS Tar Hollow Resurf ODNR FY20 | Preventive Maintenance | 2020 |
| 109380 | ROS Tar Hollow Culvert ODNR FY20 | Culvert Construction/Reconstr/Repair | 2020 |
| 109600 | LAW US 52 20.45 Safety | Intersection Improvement | 2020 |
| 109983 | D09 GR End Assembly Repair | Guardrail upgrade/replace | 2020 |
| 12056 | PIK-335-21.26 | Bridge Replacement | 2021 |
| 88970 | PIK-SR 32-3.04 | Resurfacing, Divided System | 2021 |
| 91549 | LAW-243-12.79 | Bridge Replacement | 2021 |
| 95432 | FACD09 JAC Jackson Salt FS | Buildings - Mix Shed,etc. | 2021 |
| 95584 | HIG-28/138/753-7.27/32.48/13.47 | Minor Rehabilitation - Pavement Prmy Sy | 2021 |
| 95603 | ADA-32-6.73 | Resurfacing, Divided System | 2021 |
| 96110 | FACD09 JAC Jackson Wash Bay FS | Buildings - Mix Shed,etc. | 2021 |
| 96120 | FACD09 SCI Wheelersburg OP | Buildings - Mix Shed,etc. | 2021 |
| 96132 | FACD09 ADA Peebles Matl Shed OP | Buildings - Mix Shed,etc. | 2021 |
| 96135 | LAW Pole Building | Buildings - Mix Shed,etc. | 2021 |
| 96289 | LAW SR 93 TR 169 Brdg Replace | Bridge Replacement | 2021 |
| 96804 | BRO SR 221 6.80 Landslide Site | Slide Repair | 2021 |
| 98005 | SCI-335-8.63 | Bridge Replacement | 2021 |
| 99197 | HIG-SR73/CR7-0.50/12.11 Safety | Intersection Improvement | 2021 |
| 99204 | PIK CR 66 4.36 | Minor Rehabilitation - Pavement Gnrl Sys | 2021 |
| 100302 | BRO-505-6.03 | Bridge Replacement | 2021 |
| 100444 | D09 Deck Sealing Project FY2021 | Bridge Maintenance | 2021 |
| 100446 | D09 PM FY2021 (A) | Pavement Marking | 2021 |
| 100447 | D09 PM FY2021 (B) | Pavement Marking | 2021 |
| 100448 | D09 RPM FY2021 | Raised Pavement Markers | 2021 |
| 100483 | ROS SR 772 10.35 | Resurfacing, Undivided System | 2021 |
| 100500 | JAC SR 93 & 139 Urban Paving | Resurfacing, Undivided System | 2021 |

| | | | |
|--------|----------------------------------|--|------|
| 100504 | HIG US 62 10.38 | Resurfacing, Undivided System | 2021 |
| 100848 | PIK-335-14.55 | Resurfacing, Undivided System | 2021 |
| 100883 | D09 Guardrail Project 2021 | Guardrail upgrade/replace | 2021 |
| 100884 | HIG-41-0.40 | Bridge Replacement | 2021 |
| 100886 | JAC-139-3.17 | Bridge Replacement | 2021 |
| 101738 | HIG-28-9.25 | Culvert Construction/Reconstr/Repair | 2021 |
| 101866 | ADA CR VAR PM FY21 | Pavement Marking | 2021 |
| 101867 | ADA CR VAR Guardrail FY21 | Guardrail upgrade/replace | 2021 |
| 101868 | LAW CR 410 Intersection | Intersection Improvement | 2021 |
| 101874 | ROS CR VAR Guardrail FY 2021 | Guardrail upgrade/replace | 2021 |
| 101880 | SCI CR VAR Guardrail FY 2021 | Guardrail upgrade/replace | 2021 |
| 102181 | LAW-775-(15.45)(15.70) | Bridge Replacement | 2021 |
| 102384 | SCI US 23 & SR 73 Portsmouth | Minor Rehabilitation - Pavement Gnrl Sys | 2021 |
| 102441 | ADA-32-23.22 | Culvert Construction/Reconstr/Repair | 2021 |
| 102442 | BRO-50-3.95 Geotech | Culvert Construction/Reconstr/Repair | 2021 |
| 102853 | D09 Bridge Maintenance FY21 | Bridge Maintenance | 2021 |
| 102890 | D09 FY21 Invert | Culvert Construction/Reconstr/Repair | 2021 |
| 103776 | BRO Village of Aberdeen SRTS | School Entrance Improvements | 2021 |
| 104155 | PIK SR 772 13.77 Slide Repair | Slide Repair | 2021 |
| 104159 | LAW SR 7 4.10 Rockfall | Rock Slope Maintenance (NEW) | 2021 |
| 104878 | SCI-52-2.44 & 10.15 | Bridge Replacement | 2021 |
| 104880 | BRO-774-10.56 | Bridge Replacement | 2021 |
| 104881 | SCI-348-9.42 | Bridge Replacement | 2021 |
| 105313 | BRO CR 76 5.52 Brdg Replace | Bridge Replacement | 2021 |
| 106638 | SCI Riverfront Multi-Use Path | Bikeways | 2021 |
| 106902 | ADA SR 781 6.60/7.40 Geotech | Slide Repair | 2021 |
| 107132 | BRO-41-3.34 Safety | Section Improvement | 2021 |
| 107243 | LAW SR 7 1.62 Slide Repair | Slide Repair | 2021 |
| 107294 | ROS SR 28 0.00-6.00 | Resurfacing, Undivided System | 2021 |
| 107640 | SCI-348-6.56 | Bridge Replacement | 2021 |
| 107862 | ADA/BRO-136/62-18.96/26.50 | Turn Lane Addition | 2021 |
| 108284 | BRO US 52 15.20 OH18-01 | Culvert Construction/Reconstr/Repair | 2021 |
| 108290 | ROS SR 772 10.30 OH18-01 | Slide Repair | 2021 |
| 108463 | PIK CR 50 3.40 OH18-01 | Slide Repair | 2021 |
| 109290 | ODNR Pike Lake State Park | Resurfacing, Undivided System | 2021 |
| 109342 | SCI Scioto SF Resurf ODNR FY21 | Preventive Maintenance | 2021 |
| 109343 | SCI Shawnee State Forest Culvert | Culvert Construction/Reconstr/Repair | 2021 |
| 109344 | ROS Tar Hollow Culvert ODNR FY21 | Culvert Construction/Reconstr/Repair | 2021 |
| 109360 | ROS-327-3.88 | Culvert Construction/Reconstr/Repair | 2021 |
| 109361 | JAC-139-2.70 | Culvert Construction/Reconstr/Repair | 2021 |
| 109376 | D09 Tranquility ODNR FY21 | Preventive Maintenance | 2021 |
| 109382 | ROS Tar Hollow Slips ODNR FY21 | Slide Repair | 2021 |
| 109383 | ROS Scioto SF Bridge ODNR FY21 | Preventive Maintenance | 2021 |
| 109601 | BRO US 68 30.82 Safety | Intersection Improvement | 2021 |
| 109627 | BRO US 52 2.51 OH18-02 | Slide Repair | 2021 |
| 109629 | BRO SR 41 1.06 OH18-02 | Slide Repair | 2021 |
| 109631 | BRO SR 41 2.09 OH18-02 | Slide Repair | 2021 |

| | | | |
|--------|----------------------------------|--------------------------------------|------|
| 109632 | BRO SR 41 2.81 OH18-02 | Slide Repair | 2021 |
| 109633 | BRO SR 41 3.36 OH18-02 | Slide Repair | 2021 |
| 109635 | BRO SR 41 4.18 OH18-02 | Slide Repair | 2021 |
| 109822 | BRO SR 125 0.00 Overlay | Resurfacing, Undivided System | 2021 |
| 109823 | BRO-286/763/774-0.00 | Preventive Maintenance | 2021 |
| 109824 | HIG SR 41 2.41 | Preventive Maintenance | 2021 |
| 109838 | JAC SR 32 0.00 | Resurfacing, Undivided System | 2021 |
| 109842 | LAW-243/378-11.59/0.00 | Resurfacing, Undivided System | 2021 |
| 109843 | ROS SR 104 18.68 | Resurfacing, Undivided System | 2021 |
| 109845 | SCI/LAW-US 52-33.82/0.00 | Resurfacing, Undivided System | 2021 |
| 109973 | PIK US 23 11.11 Signal | Signals | 2021 |
| 75923 | LAW Chesapeake Bypass Phase 2 | Bypass | 2022 |
| 87266 | PIK US 23 0.00 | Resurfacing, Divided System | 2022 |
| 91067 | LAW Union Rome Trails & Walkways | Bikeways | 2022 |
| 93830 | HIG SR 247 0.04 Brdg Replace | Bridge Replacement | 2022 |
| 93832 | HIG SR 134 7.82 Brdg Replace | Bridge Replacement | 2022 |
| 95604 | JAC US 35 19.00 | Resurfacing, Divided System | 2022 |
| 96107 | FACD09 PIK Salt Shed Enclosed FS | Buildings - Mix Shed,etc. | 2022 |
| 96294 | HIG-247-0.00 | Resurfacing, Undivided System | 2022 |
| 98149 | ROS-50-0.00 | Preventive Maintenance | 2022 |
| 100502 | HIG-50/134-0.00/12.28 | Resurfacing, Undivided System | 2022 |
| 100891 | SCI-139-11.38 | Bridge Replacement | 2022 |
| 100896 | BRO SR 763 1.51 Brdg Replace | Bridge Replacement | 2022 |
| 100900 | HIG-73-17.22 Chip Seal | Preventive Maintenance | 2022 |
| 102270 | ROS Industrial Parkway Phase 2 | New Construction | 2022 |
| 102449 | LAW SR 217 17.38 Culvert | Culvert Construction/Reconstr/Repair | 2022 |
| 102844 | D09 Guardrail Project 2022 | Guardrail upgrade/replace | 2022 |
| 102845 | D09 PM FY2022 (A) | Pavement Marking | 2022 |
| 102846 | D09 PM FY2022 (B) | Pavement Marking | 2022 |
| 102847 | D09 RPM FY2022 | Raised Pavement Markers | 2022 |
| 102848 | D09 Deck Sealing Project FY2022 | Bridge Maintenance | 2022 |
| 102854 | D09 Bridge Maintenance FY22 | Bridge Maintenance | 2022 |
| 103975 | LAW SR 141 16.94 Brdg Replace | Bridge Replacement | 2022 |
| 103977 | HIG SR 72 2.30 Brdg Replace | Bridge Replacement | 2022 |
| 104680 | ADA CR VAR Guardrail FY22 | Guardrail upgrade/replace | 2022 |
| 104681 | ADA CR VAR PM FY22 | Pavement Marking | 2022 |
| 104683 | JAC CR VAR GR FY22 | Guardrail upgrade/replace | 2022 |
| 104686 | ROS CR VAR PM FY22 | Pavement Marking | 2022 |
| 104687 | SCI CR 253 0.00 Widening | Widening | 2022 |
| 104688 | SCI CR 2 0.00 Widening | Widening | 2022 |
| 105097 | PIK 23 15.35 Liner | Culvert Construction/Reconstr/Repair | 2022 |
| 105100 | SCI SR 239 0.98 Brdg Replace | Bridge Replacement | 2022 |
| 105103 | ROS-138-10.98 Culvert | Culvert Construction/Reconstr/Repair | 2022 |
| 105113 | BRO SR 221 5.54 Brdg Replace | Bridge Replacement | 2022 |
| 106540 | PIK CR 9 5.29 Bridge Replace | Bridge Replacement | 2022 |
| 107244 | BRO US 52 16.22 Slide | Slide Repair | 2022 |

| | | | |
|--------|----------------------------------|--------------------------------------|------|
| 107639 | ADA-770-10.31 | Bridge Replacement | 2022 |
| 107642 | JAC-788-4.69 | Bridge Replacement | 2022 |
| 107722 | ADA-41-22.50 Slide | Slide Repair | 2022 |
| 108129 | PIK-CR50-3.32 OH16-01 | Slide Repair | 2022 |
| 108464 | PIK CR 50 2.55 OH18-01 | Slide Repair | 2022 |
| 108735 | JAC CR 501 0.73 Bridge Replace | Bridge Replacement | 2022 |
| 108904 | HIG US 50/Main Street Sidewalks | Add Sidewalks | 2022 |
| 108922 | HIG Lynchburg Covered Bridge | Bridge Maintenance | 2022 |
| 109199 | LAW-52-22.09 Geotech | Slide Repair | 2022 |
| 109200 | ROS-41-5.50 Geotech | Slide Repair | 2022 |
| 109440 | BRO CR 62 0.42 Brdg Replace | Bridge Replacement | 2022 |
| 109573 | ADA-41-32.24 Culvert | Culvert Construction/Reconstr/Repair | 2022 |
| 109574 | ADA-247-21.18 Culvert | Culvert Construction/Reconstr/Repair | 2022 |
| 109575 | HIG-138-5.60 Culvert | Culvert Construction/Reconstr/Repair | 2022 |
| 109577 | JAC-327-12.95 Culvert | Culvert Construction/Reconstr/Repair | 2022 |
| 109820 | ADA-137/770-0.00/0.34 Thinlay | Preventive Maintenance | 2022 |
| 109825 | HIG SR 73 0.00 | Resurfacing, Undivided System | 2022 |
| 109834 | LAW SR 775 9.53 | Preventive Maintenance | 2022 |
| 109837 | HIG SR 138 0.00 | Resurfacing, Undivided System | 2022 |
| 109840 | JAC SR 93 14.29-15.57 | Resurfacing, Undivided System | 2022 |
| 109841 | JAC SR 32 6.40 | Preventive Maintenance | 2022 |
| 109844 | ROS SR 180 2.00 | Resurfacing, Undivided System | 2022 |
| 109846 | SCI US 23 2.67 | Resurfacing, Undivided System | 2022 |
| 109921 | BRO SR 32 0.00 | Resurfacing, Undivided System | 2022 |
| 87333 | HIG SR 138 27.24 Deck Replace | Bridge Deck Replacement | 2023 |
| 91412 | ADA SR 348 12.09 Bridge Replace | Bridge Replacement | 2023 |
| 93834 | HIG SR 138 23.62 Brdg Replace | Bridge Replacement | 2023 |
| 96948 | JAC US 35 4.33 Brdg Liner | Bridge Repair | 2023 |
| 98321 | D09 Smoothseal FY23 | Resurfacing, Undivided System | 2023 |
| 98961 | LAW Multi-Modal Parking Deck/Fac | Transit | 2023 |
| 100492 | D09 Overlay w/ Repairs FY23 | Resurfacing, Divided System | 2023 |
| 100854 | D09 Overlay FY23 | Resurfacing, Undivided System | 2023 |
| 100893 | SCI SR 140 7.65 Brdg Replace | Bridge Replacement | 2023 |
| 100894 | D09 Bridge Painting FY23 | Bridge Painting | 2023 |
| 100895 | D09 Deck Overlay FY23 | Bridge Repair | 2023 |
| 102911 | ROS 207 9.32 Culvert | Culvert Construction/Reconstr/Repair | 2023 |
| 103780 | JAC CR 85 0.21 Brdg Replace | Bridge Replacement | 2023 |
| 103781 | LAW CR 104 2.40 Brdg Replace | Bridge Replacement | 2023 |
| 104879 | SCI US 23 16.51 Bridge Repair | Bridge Repair | 2023 |
| 104882 | D09 RPM FY2023 | Raised Pavement Markers | 2023 |
| 104883 | D09 PM FY2023 (A) | Pavement Marking | 2023 |
| 104884 | D09 PM FY2023 (B) | Pavement Marking | 2023 |
| 104885 | D09 Guardrail Project FY2023 | Guardrail upgrade/replace | 2023 |
| 104886 | D09 Bridge Maintenance FY23 | Bridge Maintenance | 2023 |
| 104887 | D09 Deck Sealing Project FY2023 | Bridge Maintenance | 2023 |
| 105102 | PIK SR 776 0.05 Brdg Replace | Bridge Replacement | 2023 |

| | | | |
|--------|--------------------------------|--------------------------------------|------|
| 105104 | D09 Culvert Project FY23 | Culvert Construction/Reconstr/Repair | 2023 |
| 105108 | SCI SR 125 2.90 Brdg Replace | Bridge Replacement | 2023 |
| 105109 | SCI SR 335 12.02 Brdg Replace | Bridge Replacement | 2023 |
| 105111 | HIG SR 73 0.30 Brdg Replace | Bridge Replacement | 2023 |
| 106544 | ROS CR 222 3.83 Bridge Replace | Bridge Replacement | 2023 |
| 107071 | ADA CR VAR Guardrail FY23 | Guardrail upgrade/replace | 2023 |
| 107072 | ADA CR VAR PM FY23 | Pavement Marking | 2023 |
| 107073 | HIG CR VAR Guardrail FY23 | Guardrail Maintenance/Repair (NEW) | 2023 |
| 107074 | HIG CR Various PM FY 2023 | Pavement Marking | 2023 |
| 107075 | JAC CR VAR PM FY2023 | Pavement Marking | 2023 |
| 107331 | HIG VAR CR Resurfacing FY23 | Resurfacing, Undivided System | 2023 |
| 107638 | ADA-247-3.55 Bridge | Bridge Replacement | 2023 |
| 107641 | ROS-180-4.54 Bridge | Bridge Replacement | 2023 |
| 107643 | SCI-335-6.09 Bridge | Bridge Replacement | 2023 |
| 109856 | D09 Chip Seal FY23 | Preventive Maintenance | 2023 |
| 109857 | D09 Double Micro FY23 | Preventive Maintenance | 2023 |

The FY20-23 Capital Programs Work Plan is produced by the Ohio Department of Transportation - District 9. The preceding summary is a draft outline of those projects which are being programmed or considered for construction during fiscal years 2020 through 2023. All projects listed are subject to change, and due to planning, design and funding variables, not all projects may be sold as proposed.



**OHIO DEPARTMENT OF
TRANSPORTATION**