

Ohio Department of Transportation - Prebid Questions

Project No. 160133

Sale Date - 3/24/2016

ALL-90849 - SR 309-0.00 (PART 1 AND PART 2)

Question Submitted: 3/21/2016 10:27:58 AM

The general summary refers us to page 12 for Type 2 Curb and Gutter as per plan, but there are no notes for this item. Please clarify.

The general summary reference to Sheet 12 is incorrect. Plan Sheet 32 has been corrected to show a reference to Sheet 175 for the Type 2 Curb and Gutter, As Per Plan, item.

Question Submitted: 3/20/2016 8:17:34 PM

The sign support quantities in the general summary do not match the details shown on plan pages 210 & 211. Pay item # 135 has a quantity of two TC-16.21 design 11 sign supports but the details only show 1. Also, the details show sign support OHS5 as a TC-16.21 design 8, which does not have a pay item. Can an addendum be issued to clarify the sign support quantities?

This question has been addressed in Addendum No. 2. Please refer to Addendum No. 2.

Question Submitted: 3/18/2016 11:26:44 AM

In order to bid competitively, it may be difficult for some contractors to perform 50% of the work type by the prime contractor. For more competitive bids, could this percentage be lowered to 30%?

After review it has been decided that the percentage will remain at 50%

Question Submitted: 3/17/2016 4:20:51 PM

Ref #0111 Asphalt Concrete Intermediate Course,19MM, Type A(446)has 787 CY set up to be used in the widening from STA 326+38-458+50 and the culvert at STA 35+00. Due to the variable width construction and small lots that that will be placed on a daily basis please consider adding this quantity to Ref #0112 Asphalt Concrete Intermediate Course,19MM, Type A (448). This would eliminate the need to cut cores in widening area & culvert.

This question will be addressed with a forth coming addendum.

Question Submitted: 3/14/2016 9:30:45 AM

Some of the pipe and structure quantities and descriptions in the General Summary do not match the plan sheets and profile sheets. Can these items be reviewed and revised.

To better understand and address the subject question, please provide further clarification on what quantities, descriptions and/or items/reference number are being questioned, along with the sheet numbers of the related plan and profile sheets?

Question Submitted: 3/10/2016 3:49:47 PM

The overhead sign supports shown on sub summary sheets 187 & 188 do not match the details shown on sheet 210.

This question will be addressed with a forth coming addendum.

Question Submitted: 3/2/2016 10:22:36 AM

Page 212 of the plans (traffic control notes) calls for sign supports to be painted in accordance with the requirements shown on sheet 125. Sheet 125 is cross section details. Looking elsewhere in the plans (general notes, etc.)the paint requirements can't be found. Please advise what is required.

This question will be addressed with a forthcoming addendum.