

# Ohio Department of Transportation - Prebid Questions

Project No. 160507

Sale Date - 9/22/2016

ASD-98400 - SR 95-01.46

*Question Submitted:* 9/16/2016 3:55:08 PM

Please indicate a proposed breakdown of transverse vs. longitudinal repairs for Ref. 1, 251 Partial Depth Pavement Repair. There is a large difference in cost between the two methods.

**For Item 251 – Partial Depth Pavement Repair, approximately 10% of the quantity is estimated for transverse repairs, and approximately 90% of the quantity is estimated for longitudinal repairs.**

*Question Submitted:* 9/13/2016 10:21:14 AM

No line items for RPM removal or RPM installation has been provided. Historically ODOT has provided line items for RPM removal and RPM installation. Is it the intention for these items to be incidental to the single chip seal or will ODOT provide these line items?

**The cost of any removal and replacement, or protection of existing raised pavement markers on a single chip seal according to C&MS 422.06 is incidental to the chip seal item.**