

Ohio Department of Transportation - Prebid Questions

Project No. 150331

Sale Date - 6/4/2015

BEL-91866 - IR 70-5.92

Question Submitted: 6/1/2015 11:39:23 AM

Reference # 119 & 151 do not add up to what is shown in the plans and plan note for piles furnished. Also reference #154 & 122 quantities seem to be over what is called out in the plans. We are coming up with 170 each of steel points. Please advise.

Question Submitted: 5/29/2015 5:01:11 PM

Please describe locations and depths for the abutment prebored holes, ref. 121 and 153.

Question Submitted: 5/29/2015 1:48:24 PM

The quantities for Ref numbers 129 and 161 QC1 Footer Concrete are incorrect. The quantities are too high.

The quantities will be corrected by addendum.