

Ohio Department of Transportation - Prebid Questions

Project No. 163021

Sale Date - 4/21/2016

BEL-97842 - OBPP CR 4 23.52/TR 291 0.01

Question Submitted: 4/13/2016 2:44:26 PM

For the CR4 site, can ODOT clarify the removal limits of the existing stone retaining wall at the forward abutment right side? Is the intent for that wall to remain as it does not appear to be connected to the existing cast-in-place abutment.

The DBT will need to remove as much wall as is necessary to build their proposed structure. The stability of the remaining wall cannot be compromised. Any damage to the existing stone wall beyond the DBT's structure is to be repaired/replaced.