

# Ohio Department of Transportation

## Prebid Questions

Project No. 100004

Sale Date - 1/28/2010

Question Submitted: 1/12/2010

Question Number: 1

THE QUANTITY OF 13,600FT FOR 1-1/2" CABLE DUCT ITEM # 90 SEEMS TO BE SUBSTANTIALLY IN ERROR. THE QUANTITY SHOWN ON PLAN SHEET # 50 THRU 60 AND ALSO ON PLAN SHEET 154 THRU 163 ADDS TO ONLY 4550 FEET. IT SEES THAT PROPOSAL QUANTITY IS 3 TIMES THE QUANTITY ACTUALLY REQUIRED. ALSO THE TRENCH ITEM # 93 SHOULD BE 4550 FT & NOT 5500 FT THIS ERROR COULD RESULT IN SUBSTANTIAL ERROR IN THE BID. PLEASE ADVISE OR ISSUE AN ADDENDUM. THANK YOU

**A: These items have been reevaluated by the consultant and revised by an addendum.**

Question Submitted: 1/13/2010

Question Number: 2

DEAR ODOT, I AM LOOKING FOR THE SPECIFICATION FOR A SPECIAL - GEOGRID FOR THE I-74 PROJECT #100004 PID#:78083. THE PRODUCT NUMBER IS:690E12020. I LOOK FORWARD TO YOUR RESPONSE. THANK YOU FOR YOUR CONSIDERATION. SINCERELY, J. ERIC SPANGLER 317.557.1220

**The material and installation requirements for the geogrid to be utilized in the geogrid reinforced soil embankment are specified on Sheets 126 through 128 of the plan documents.**

Question Submitted: 1/6/2010

Question Number: 3

Currently, the project requires that 50% of the work be performed by the Prime Contractor. Due to the size of the signal work required for this project, will the percentage requirement be adjusted?

**The requirement will remain at 50%.**

Question Submitted: 1/7/2010

Question Number: 4

Bid references # 82 through 84 are for convention design light poles AT15B41.6, AT20B41.7, & AT25B41.8 respectively, which each contain a luminaire bracket arm as part of the standard design. Bid references # 86 through 87 appear to be separate pay items for the same luminaire arm brackets which would be included with poles bid references 82 through 84. Are these additional brackets required or are these duplicate items that should be eliminated? If required, what pole locations are these to be installed on?

**The Bracket Arms listed were duplicated pay items that have been deleted by addendum.**

Question Submitted: 1/9/2010

Question Number: 5

Ref No. 105 specifies that there are 50 ea bracket mounted delineators. Typically per ODOT Standard these are mounted on bridges. Since there are no bridges in the area that the delineators are to be mounted what surface are these delineators to be mounted?

**See Addendum**

Question Submitted: 12/18/2009

Question Number: 6

Could all of the electronic files be made available (DGN, geopak, ect.)?

**Electronic files in the DGN format are not available for this project. It is ODOT-let but locally sponsored and the consultant was not required to submit the project in the traditional Microstation format. The electronic design files have been placed on the shared server (\\CTRF100\D08\DGN) Folder : HAM-78083**

All prospective bidders, subcontractors, suppliers, materialmen and all others who have an interest in these prebid questions and answers are advised that these items are being provided for informational purposes only and are not part of the bidding documents. If a question warrants a clarification, the Department will issue an addenda addressing the request for clarification to all plan holders. If the Department believes that the bidding documents adequately address the request, the contractor will be advised accordingly.