

Ohio Department of Transportation

Prebid Questions

Project No. 090092

Sale Date - 2/4/2009

Question Submitted: 2/10/2009

Question Number: 1

On all the bridges on this project receiving new concrete sealer there is existing gray concrete sealer, will the department require 100% removal of this existing concrete sealer?

The concrete is to be prepared for the new sealer according to CMS 512.03F. This requires the following: "Remove dust, dirt, oil, wax, curing compounds, efflorescence, laitance, coatings and other foreign materials from surfaces to be sealed".

Question Submitted: 2/10/2009

Question Number: 2

Could you please provide clarification to the cross section drawing for Item 251 - Partial Depth Pavement Repair on page 3 of the plans. The note referring to the depth above the drawing states "*** 4" OR TO THE TOP OF THE CONCRETE, WHICHEVER COMES FIRST". There is also a note which is part of the drawing that appears to reference the width of the repair stating, "PARTIAL DEPTH REPAIR (4" MIN)". If this is in fact referring to the width of the repair it appears to be in error. If it is referring to the depth of the repair, it is in conflict with the previous note. Could you please provide clarification on this matter. Thank you.

All prospective bidders, subcontractors, suppliers, materialmen and all others who have an interest in these prebid questions and answers are advised that these items are being provided for informational purposes only and are not part of the bidding documents. If a question warrants a clarification, the Department will issue an addenda addressing the request for clarification to all plan holders. If the Department believes that the bidding documents adequately address the request, the contractor will be advised accordingly.